

Preparation for installation


Prior to laying, please store Kronotex flooring horizontally in unopened packaging at room temperature for a minimum of 48 hours so that all planks have enough time to reach room temperature.


The following ambient conditions should prevail previous to, during, and three days following installation:


Floor surface: min. 15°CAir temperature: min. 18°C

Humidity: 50 - 75%


















Laminate Installation Instructions and Considerations:














KRONOTEX






























Laminate Care and Maintenance

